

Ref. No.: MN – 21-0076
Certificate No.: MN-21-0722 / 1 of 6

Alexandria on: 26/04/2021

INSPECTION CERTIFICATE

Client : Marmox Egypt Co.- chemicals For Modern Building International (CMBI)
Place of Inspection : Factory Of Marmox Egypt Co. at Wadi El Natrone Industrial Zone.
Date Of Inspection : 7th of April, 2021
Goods : Manholes and Grids Covers
Quantity : 221 pieces
Scope of Inspection : 1. Quantity check.
2. Packing.
3. Marking check.
4. visual inspection.
5. Sampling for Laoding Test.
6. Document review.

We attended to the factory of Marmox Egypt Co. at Wadi El Natrone Industrial Zone on the date 7/4/2021 and we carried out the above mentioned scope of inspection and we now report:

1. Quantity Check :


The quantities of the manhole and Grid covers were checked and found to be as per packing list received from CMB which is as follows :

-----End Of Page-----



This certificate reflect our findings at time. Date, and place of inspection only and within the limits of the client's instructions. This certificate is issued by the company under its general conditions for inspection and testing services (available up on request).The issuance of this certificate does net exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sale. Stipulations to the contrary are not binding on the company . The company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission.Expect by special arrangement, samples, if drawn, will not be retained by the company for more three months.


No. 06048



Ref. No.: MN – 21-0076

Certificate No.: MN-21-0722 / 2 of 6

Alexandria on: 26/04/2021



كيماويات البناء الحديث الدولية
CHEMICALS FOR MODERN BUILDING INTERNATIONAL

LMS - Dr. Lietz Marketing Services GmbH
Wackenbergstr. 65 - 75
D - 13156 Berlin, Germany
Tel. : +49 - (0)30 - 477 50 350
Fax: +49 - (0)30 - 477 11 41
Attn. : Mr. Uwe Lietz

PACKING LIST

No.: 000000000

From: Any Egyptian port, Egypt.

Delivery Term: CIF

Order No.: LMSPoland order – 316 + 317-2021

EUR.1 Certificate No.: 00000000

Date : 0000000

To: Hamburg port, Germany

Containers : 1 x 40 ft. H.C

CNTR . No. : 00000000

S.	Description	QTY.	Unit	Total No. of Pcs	No. of Parcels	Parcel type	No. of pcs /parcel
1	MARMOX Manhole cover A15 - RD 600 cover with frame, , with rubber layer *	30.00	pc	30.00	1	pallet	30.00
2	MARMOX Manhole cover B125 - RD 600 cover with frame, , with rubber layer *	18.00	pc	18.00	1	pallet	18.00
3	MARMOX Manhole cover C250 - RD 600 cover with frame, with rubber layer *	17.00	pc	17.00	1	pallet	17.00
4	MARMOX Manhole cover D400 - RD 600 cover with frame, with rubber layer *	13.00	pc	13.00	1	pallet	13.00
5	MARMOX Manhole GRID C250 - BK67 cover without frame, with rubber layer	15.00	pc	15.00	1	pallet	15.00
6	MARMOX Manhole GRID C250 - BK67 cover without frame, with rubber layer	16.00	pc	16.00	1	pallet	16.00
1	MARMOX Manhole GRID D400 - BK67 with realbud marking cover without frame, with rubber layer	69.00	pc	69.00	3	pallet	23.00
2	MARMOX Manhole GRID D400 - BK67 with realbud marking cover without frame, with rubber layer	24.00	pc	24.00	1	pallet	24.00
3	MARMOX Manhole cover D400 - RD 640 cover without frame, without rubber *	10.00	pc	10.00	1	pallet	10.00
4	MARMOX Manhole cover D400 - RD 640 cover without frame, without rubber *	9.00	pc	9.00	1	pallet	9.00
5	opening tool, 1 pc. for 30 covers free of charge	3.00	pc	3.00	1	pallet	3.00

No of parcels : 13 Parcels

Gross Weight : Tons

Net Weight : Tons.

Country of origin : EGYPT .

Imp. & Exp. Manager
Soha Mohamed

43 El Haram St., - Giza Tel.: (+202) 33870911 Fax: (+202) 33847277
319 El Haram St., - Giza Tel.: (+202) 35853917 Fax: (+202) 35859858

٤٣ شارع الهرم - الجيزة تليفون: ٣٣٨٧٠٩١١ (+٢٠٢) فاكس: ٣٣٨٤٧٢٧٧ (+٢٠٢)
٣١٩ شارع الهرم - الجيزة تليفون: ٣٥٨٥٣٩١٧ (+٢٠٢) فاكس: ٣٥٨٥٩٨٥٨ (+٢٠٢)

16172 www.cmb.eg - cmb@cmbegypt.com - export@cmbegypt.com - f/cmb.eg

-----End Of Page-----

This certificate reflect our findings at time, Date, and place of inspection only and within the limits of the client's instructions. This certificate is issued by the company under its general conditions for inspection and testing services (available up on request). The issuance of this certificate does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sale. Stipulations to the contrary are not binding on the company. The company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Expect by special arrangement, samples, if drawn, will not be retained by the company for more three months.

No. 06043

Ref. No.: MN – 21-0076
Certificate No.: MN-21-0722 / 3 of 6

Alexandria on: 26/04/2021

2. Packing :

At time of inspection, the manholes and grids pieces were packed over wooden pallets and wrapped by stretch plastic cover.



3. Marking check :

The manholes and grids were found to be casting stamped by the following marks :

- www.realbud.com
- MARMOX
- Number of related specification
- Load Class

The following photos are example of marking :

-----End Of Page-----



Ref. No.: MN – 21-0076
 Certificate No.: MN-21-0722 / 4 of 6

Alexandria on: 26/04/2021



Each pallet was labeled by the number of pieces, load class, size, MARMOX and www.realbud.com



4. Visual inspection :

Samples of each manholes and grids were visually inspected and found to be newly produced products of good apparent condition.

-----End Of Page-----



This certificate reflect our findings at time, Date, and place of inspection only and within the limits of the client's instructions. This certificate is issued by the company under its general conditions for inspection and testing services (available up on request).The issuance of this certificate does net exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sale. Stipulations to the contrary are not binding on the company . The company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission.Expect by special arrangement, samples, if drawn, will not be retained by the company for more three months.

No. 06045


Ref. No.: MN – 21-0076
 Certificate No.: MN-21-0722 / 5 of 6

Alexandria on: 26/04/2021



5. Sampling for Loading Test :

We randomly selected seven samples (one sample from each type), and were delivered by CMB representative in the presence of our inspector to the Concrete, Construction Test Laboratory at the “ Housing and Building National Research Center ” for load tested in accordance to its relative standards. The following are photos of some samples :



-----End Of Page-----



This certificate reflect our findings at time. Date, and place of inspection only and within the limits of the client's instructions. This certificate is issued by the company under its general conditions for inspection and testing services (available up on request). The issuance of this certificate does net exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the contract of sale. Stipulations to the contrary are not binding on the company . The company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission.Expect by special arrangement, samples, if drawn, will not be retained by the company for more three months.

No. 06046

Ref. No.: MN – 21-0076
Certificate No.: MN-21-0722 / 6 of 6

Alexandria on: 26/04/2021

6. Document Review :

Test report issued by Concrete Construction Test Laboratories (CCTL) said to all the seven samples was carried out in accordance to ES 4207-5/2020 - EN 124-5/2015 and the samples was subjected to the following loads with no cracks observed :

1. For sample no. CI 550, manhole cover A15 - RD600, a load test of 1.5 ton with no crack and a deflection of 0.32 mm.
2. For sample no. CI 551, manhole cover B125 - RD600, a load test of 12.5 ton with no crack and a deflection of 0.69 mm.
3. For sample no. CI 552, manhole cover C250 - RD600, a load test of 25 ton with no crack and a deflection of 0.92 mm.
4. For sample no. CI 553, manhole cover D400 - RD600, a load test of 40 ton with no crack and a deflection of 1.1 mm.
5. For sample no. CI 554, manhole Grid D400 - BK67, a load test of 40 ton with no crack and a deflection of 0.95 mm.
6. For sample no. CI 555, manhole Grid C250 - BK67, a load test of 25 ton with no crack and a deflection of 0.69 mm.
7. For sample no. CI 556, manhole cover D400 - RD640, a load test of 40 ton with no crack and a deflection of 1.21 mm.

Attachments :

Attached to the certificate a copy of test report from Concrete Construction Test Laboratory (CCTL) dated 18/4/2021.

-----End Of Page-----

